




# ArgoGraph® 46510

## Urethane Overlaminates Film

### Application Recommendations For Graphic Overlamination



**NOTE: REMOVE PREMASK (PET) CARRIER FOR BOTH (1) AND (2) @ ~120°ANGLE. ONCE PREMASK (PET) CARRIER IS REMOVED, AVOID URETHANE-TO-URETHANE CONTACT DURING PACKAGING/SHIPMENT OF FINISHED OVERLAMINATED GRAPHICS DUE TO TENDENCY OF BLOCKING.**

Revised: September 16, 2016

All statements, product characteristics, and performance data contained herein are believed to be reliable based on observation and testing, but no representations, guarantees, or warranties of any kind are made as to accuracy, suitability for particular applications, or the results to be obtained. Nothing contained herein is to be considered to be permission or a recommendation to use any proprietary process or technology without permission of the owner. No warranty of any kind, expressed or implied, is made or intended.

SWM INTL • 53 Silvio O. Conte Drive • Greenfield MA 01301  
 Tel: 413/772-2564 • Fax: 413/772-2565 • E-mail: ams@swmintl.com